

Threading Equipment

Power Threading / Geared Threaders

Power Threading with Geared Threaders – Nos. 141, 161
– Close couple method of threading.



700 Power Drive

700 Power Drive Application for 141 and 161 Geared Threader requires:

- 774 Square Drive Adapter (see pg. 28)
- 460 Tri-Stand (see pg. 16)
- 418 Oiler (see pg. 34)



300 Front-Mount

300 Power Drive Front-Mount Application for 141 and 161 Geared Threader requires:

- 1206 Stand
- Pipe Support (see pg. 54)
- 418 Oiler (see pg. 34)
- 844 Drive Bar (see pg. 33)
- 758 Loop – for 141 (see pg. 33)
- 346 Support Arms – for 161 (see pg. 33)

300 Power Drive Rear-Mount Application for 141 and 161 Geared Threader requires:

- 1206 Stand
- 460 Tri-Stand (see pg. 16)
- 418 Oiler (see pg. 34)
- 840A Universal Drive Shaft (see pg. 33)



535 Rear-Mount

535 Threading Machine Front-Mount Application for 141 Geared Threader requires:

- 844 Drive Bar (see pg. 33)
- 768 Drive Link Assembly (see pg. 33)

535 Threading Machine Rear-Mount Application for 141 and 161 Geared Threader requires:

- 460 Tri-Stand (see pg. 16)
- 418 Oiler (see pg. 34)
- 840A Universal Drive Shaft (see pg. 33)

Threading Equipment

Power Threading / Geared Threaders

300 Compact Threading Machine Front-Mount Application for

141 Geared Threader requires:

- 844 Drive Bar (see below)
- 768 Drive Link Assembly (see below)

300 Compact Threading Machine Rear-Mount Application for

161 Geared Threader requires:

- 840A Universal Drive Shaft (see below)
- 460 Tri-Stand (see pg. 16)
- 418 Oiler (see pg. 34)

1822 Threading Machine

Front-Mount Application for

141 Geared Threader requires:

- 241 Carriage Mount Kit (see pg. 44)

1224 Threading Machine

Rear-Mount Application for

161 Geared Threader requires:

- 840A Universal Drive Shaft (see below)
- 460 Tri-Stand (see pg. 16)
- 418 Oiler (see pg. 34)

Accessories For Nos. 141, 161 Geared Threaders (See Pages 31-33)




No. 840A Universal Drive Shaft

A telescoping (41" to 50") drive shaft for operation of Nos. 141 and 161 geared threaders with threading machines.

Geared Threader Operation

The Nos. 141 and 161 geared threaders, in conjunction with these accessories, allow power drives and threading machines to thread up to 4" and 6" pipe.

Catalog No.	Model No.	Description	Weight	
			lb.	kg
61122	840A	Universal Drive Shaft	26	11,8
19366	758	Loop (300)	1 ¹ / ₄	0,6
40005	346	Support Arms (300)	10 ¹ / ₂	4,8
42405	844	Drive Bar (300, 535)	5 ³ / ₄	2,6
42415	768	Drive Link Assembly (535)	2 ¹ / ₂	1,1



No. 346
Support Arms



No. 758
Loop



No. 844
Drive Bar